



State of Utah

DEPARTMENT OF ENVIRONMENTAL QUALITY DIVISION OF WATER QUALITY

Michael O. Leavitt
Governor

Dianne R. Nielson, Ph.D.
Executive Director

Don A. Ostler, P.E.
Director

288 North 1460 West
P.O. Box 144870
Salt Lake City, Utah 84114-4870
(801) 538-6146
(801) 538-6016 Fax
(801) 536-4414 T.D.D.

DOGM
MINERALS PROGRAM
FILE COPY

RECEIVED
NOV 24 1993

DIVISION OF
OIL, GAS & MINING

November 18, 1993

Mr. Dave Hodson, Manager
Barneys Canyon Mine
P.O. Box 311
Bingham Canyon, UT 84006-0311

RE: 3rd Quarter Monitoring Report, Restored
BAT at Process Ponds; Ground Water
Discharge Permit No. UGW350001

Dear Mr. Hodson:

We received your Third Quarter Monitoring report from Steve Lackey dated October 29, 1993. The information is timely, but indicates that well BC-283 still remains in an out of compliance condition. TDS is now reported at 926 mg/l where as the last reported results were 891 mg/l. Your next quarterly monitoring report should contain the information requested in our November 11, 1993 letter, and after our review we will determine what action regarding the well needs to be taken.

We understand that the HDPE liner in the pregnant and barren solution ponds was repaired as described and approved in our letter of March 22, 1993. Lyle Stott made an inspection of the liner on May 10, 1993 and approved the repairs and the rearrangement of the welded pipe extensions. BAT for the ponds is now considered to be restored.

Should you have questions, please call Mack Croft or Lyle Stott at 538-6146.

Sincerely,

Utah Water Quality Board

Don A. Ostler, P.E.
Executive Secretary

DAO:MC:gt

cc: Kent Miner, SL City/County HD
Division of Oil, Gas & Mining ✓

P:BCTHIRD.LTR
FILE:BARNEYS CANYON

Printed on recycled paper